

Selection Chart

	Page	Screwdriver					Controller								
		Series	Model	Applicable Screws	Features	Starting Method	Model	Features							
	5	5700 series	DLV5720	Miniature Screws	Low Voltage, Low Shock, ESD	Lever Start	DLC0350	Speed Control, Soft Start, Signal Output							
			DLV5720H												
			DLV5740				DLC0950								
			DLV5740H												
	6	5800 series	DLV5820		Low Voltage, ESD		Push to Start	DLC0250	Small size						
			DLV5820H												
			DLV5840												
	7	7800 series	DLV7810		Small Controller		Lever Start	DLC2110	Compact						
			DLV7820												
	8	7300 series	DLV7313-CME		Low Voltage		Lever Start	DLC1213A	Speed Control, Soft Start						
			DLV7321 / 7323-C□E												
			DLV7331 / 7333-C□E					DLC1215 DLC2310							
			DLV7325-C□E												
	9		7300 series	DLV7321-B□E	Low Voltage, Clean Room	Lever Start		DLC1215 DLC2310	Multiple Control						
				DLV7331-B□E											
				DLV7319-BME											
				DLV7329-BME											
				DLV7339-BME											
	9		7300 series	DLV7349-BME	Low Voltage, ESD	Lever Start		DLC1213A-□□B	Speed Control, Soft Start, Bit Ground						
				DLV7020						Transformerless	Lever Start	DLC3310	Torque Reach Signal Output		
				DLV7030											
		DLV7031													
	10	7000 series	DLV8020	Low Voltage, Clean Room, Low Shock, ESD	Push to Start	DLC3310	Torque Reach Signal Output								
			DLV8030												
			DLV8031												
	11	7100 series	DLV7120	Machine Screws	Lever Start	DLC3310	Torque Reach Signal Output								
			DLV7130												
			DLV7140												
			DLV7150												
	11	7200 series	DLV7220	Machine Screws	Lever Start	DLC3310	Torque Reach Signal Output								
			DLV7221												
			DLV7231												
			DLV7241												
	11	7200 series	DLV7251	Machine Screws	Lever Start	DLC3310	Torque Reach Signal Output								
			DLV8120												
			DLV8130												
			DLV8140												
	11	8100 series	DLV8150	Machine Screws	Lever Start	DLC3310	Torque Reach Signal Output								
			DLV8220												
			DLV8221												
			DLV8231												
	11	8200 series	DLV8241	Machine Screws	Lever Start	DLC3310	Torque Reach Signal Output								
			DLV8251												
								12	3300 series	DLV3321	Miniature Screws	For Robot (with Torque Reach Signal Output)	External Input	DLC3310	Torque Reach Signal Output
										DLV3331					
DLV3121															
DLV3131															
	12	3100 series	DLV3141	Machine Screws	Low Voltage	Lever Start	DLC4511-GGB	Speed Control, Soft Start, Bit Ground, Signal Output							
			DLV3151												
			DLV7530												
			DLV7540												
	13~14	7500 series	DLV7550	Machine Screws	Low Voltage	Lever Start	DLC4511-GGB	Speed Control, Soft Start, Bit Ground, Signal Output							
			DLV8530												
			DLV8540			Push to Start									
			DLV8550												