

# Selection Chart

|  | Page  | Electric Screwdriver   |                             |   |                          | Controller                |                              |
|--|-------|------------------------|-----------------------------|---|--------------------------|---------------------------|------------------------------|
|  |       | Series                 | Model                       | Features  | Starting Method          | Model                     | Voltage                      |
|  | 5-6   | 7400A                  | DLV7410A/7410HA/7420A       | Bit Grounding<br>Low Shock<br>ESD               |                          | DLC1110                   | 100/115/220/<br>230/240 V AC |
|  |       |                        | DLV7419A/7419HA/7429A       | Bit Grounding<br>Low Shock<br>ESD<br>Clean Room |                          |                           |                              |
|  | 7     | 5700                   | DLV5720/5720H/5740          | Bit Grounding<br>Low Shock<br>ESD               |                          | DLC0350                   | 100/115/230 V AC             |
|  |       |                        | DLV5740H/5750               |   |                          | DLC0950                   |                              |
|  | 8     | 5800                   | DLV5820/5820H/5840          | Bit Grounding<br>ESD                            | Lever Start              | DLC0350                   | 100 V AC                     |
|  |       |                        |                             |   | DLC0250E                 |                           |                              |
|  | 9     | 7300                   | DLV7313/7321/7323/7331/7333 | Low Voltage                                     |                          | DLC1213A                  | 100/115/230/240 V AC         |
|  |       |                        | DLV7325/7335                | Clean Room                                      |                          | DLC1215                   |                              |
|  | 10    | 7300<br>BME/<br>BKE    | DLV7321-B/E                 | ESD   |                          | DLC1213A-□□B              | 100/115/<br>230/240 V AC     |
|  |       |                        | DLV7331-B/E                 |   |                          |                           |                              |
|  |       |                        | DLV7319/7329/7339/7349-BME  | Clean Room<br>Low Shock<br>ESD                  |                          |                           |                              |
|  |       |                        |                             |   |                          |                           |                              |
|  | 11    | 7000<br>8000           | DLV7020/7030/7031           | Transformerless                                 | Lever Start              |                           | 100/115 V AC                 |
|  |       |                        | DLV8020/8030/8031           |   | Push to Start            |                           |                              |
|  | 12    | 7104                   | DLV7124/7134/7144           | Transformerless                                 | Lever Start              |                           | 230 V AC                     |
|  |       |                        | DLV8124/8134/8144           |   |                          |                           |                              |
|  |       | 8104                   | DLV8154                     | Transformerless<br>High Torque                  | Push to Start            |                           |                              |
|  |       |                        |                             |   |                          |                           |                              |
|  |       | 8204                   | DLV8224/8234/8244           | Transformerless<br>High Speed                   |                          |                           |                              |
|  |       |                        |                             |   |                          |                           |                              |
|  | 13-14 | 7500                   | DLV7530/7540                | Torque Reach Light                              | Lever Start              | DLC4511-GGB<br>DLR1510-JE | 230 V AC                     |
|  |       |                        | DLV7550                     | Torque Reach Light<br>High Torque               |                          |                           |                              |
|  |       | 8500                   | DLV8530/8540                | Torque Reach Light                              | Push to Start            |                           |                              |
|  |       |                        | DLV8550                     | Torque Reach Light<br>High Torque               |                          |                           |                              |
|  | 15    | 7100                   | DLV7120/7130/7140           | Transformerless                                 | Lever Start              |                           | 115 V AC                     |
|  |       |                        | DLV7221                     | Transformerless<br>High Speed                   |                          |                           |                              |
|  |       | 7200                   | DLV7231/7241                | Transformerless<br>High Torque                  |                          |                           |                              |
|  |       |                        | DLV7251                     |   |                          |                           |                              |
|  |       | 8100                   | DLV8120/8130/8140           | Transformerless                                 | Push to Start            |                           |                              |
|  |       |                        | DLV8150                     | Transformerless<br>High Torque                  |                          |                           |                              |
|  |       | 8200                   | DLV8221                     | Transformerless<br>High Speed                   |                          |                           |                              |
|  |       |                        | DLV8231/8241                |   |                          |                           |                              |
|  |       |                        | DLV8251                     | Transformerless<br>High Torque                  |                          |                           |                              |
|  |       |                        |                             |   |                          |                           |                              |
|  | 17    | 02/12/16               | DLV02/12/16                 | Low torque                                      | Lever Start              | DLC16S-W□B                | 100 - 240 V AC               |
|  | 18    | 30/45/70               | DLV30LL/30SL/30HL           | Transformerless<br>Brushless Motor              | Lever Start              |                           | 230 V AC                     |
|  |       |                        | DLV30LP/30SP/30HP           |   | Push to Start            |                           |                              |
|  |       |                        | DLV45LL/45SL                |   | Lever Start              |                           |                              |
|  |       |                        | DLV45LP/45SP                |   | Push to Start            |                           |                              |
|  |       |                        | DLV70LL                     |   | Lever Start              |                           |                              |
|  |       |                        | DLV70LP                     |   | Push to Start            |                           |                              |
|  | 19    | 30/45/70<br>IKE        | DLV30LL/30SL/30HL-IKE       | Low Voltage<br>Brushless Motor                  | Lever Start              | DLR70S-WGB<br>DLC70S-WGB  | 100 - 240 V AC               |
|  |       |                        | DLV30LP/30SP/30HP-IKE       |   | Push to Start            |                           |                              |
|  |       |                        | DLV45LL/45SL-IKE            |   | Lever Start              |                           |                              |
|  |       |                        | DLV45LP/45SP-IKE            |   | Push to Start            |                           |                              |
|  |       |                        | DLV70LL-IKE                 |   | Lever Start              |                           |                              |
|  |       |                        | DLV70LP-IKE                 |   | Push to Start            |                           |                              |
|  | 22    | 3300<br>3100           | DLV3321/3331                | For Automation                                  | External                 | DLC3310                   | 24 V AC                      |
|  |       |                        | DLV3121/3131/3141/3151      |   | Input Signal             |                           | 100 V AC                     |
|  | 23-24 | 30/45/70<br>Automation | DLV30□A□-DJN                | Brushless Motor<br>For Automation               | External<br>Input Signal |                           | 100 V AC                     |
|  |       |                        | DLV45□A□-DKN                |   |                          |                           |                              |
|  |       |                        | DLV70LA□-DKN                |   |                          |                           |                              |
|  |       |                        |                             |   |                          |                           |                              |