

# Dedicated Screwdrivers for DLR5040A-WE and DLR5340-WE



DLV7000-SPC series



DLV8000-SPC series

## Dedicated Screwdrivers

		Miniature Screw(1.0 - 3.5 mm)						
Electric Screwdriver	Model	Lever Start	DLV7020-SPC	DLV7030-SPC	DLV7031-SPC	-----	-----	-----
		Push to Start	-----	-----	-----	DLV8020-SPC	DLV8030-SPC	DLV8031-SPC
	Input Voltage		100 V AC, 50/60 Hz					
	Torque Adjustment		Stepless					
	Torque (Nm)		0.05 - 0.55	0.3 - 1.1	0.3 - 1.0	0.1 - 0.55	0.3 - 1.1	0.3 - 1.0
	Free Speed (min <sup>-1</sup> )		900	650	1,200	900	650	1,200
	Power Consumption (W)		Approx. 25		Approx. 30	Approx. 25		Approx. 30
	Screw Size (mm)	Machine Screw	1.0 - 3.0	2.0 - 3.5	2.0 - 3.0	1.0 - 3.0	2.0 - 3.5	2.0 - 3.0
		Tapping Screw	1.2 - 2.6	2.0 - 3.0	2.0 - 3.0	1.2 - 2.6	2.0 - 3.0	2.0 - 3.0
	Bit Type (mm)							
Mass (g)		380			390			
Cord Length (m)		3 (with connector)						
Bit Grounding		Equipped as standard						

## Optional Accessories



**Torque Adjustment Cover**  
(DLW5200:DLV7100/7200/  
8100/8200-SPC  
DLW5300:DLV7000/8000-SPC)

- Tampering or accidental turning of the torque adjustment cover by an operator can be prevented
- Flanged coupling DLW9011 can not be mounted on SPC type



**Pistol Grip**  
(DLW2300:DLV7100/7200/  
8100/8200/30/45/70-SPC)

- Suitable for horizontal operation

TD04061 SPC cord for commercial power source (optional)



Dedicated screwdrivers can be directly plugged in commercial power source.



DLV7100/7200-SPC series



DLV8100/8200-SPC series



DLV7251-SPC



DLV8150/8251-SPC



DLV30LP-SPC



DLV30SP-SPC



DLV30HP-SPC



DLV45SL-SPC



DLV70LP-SPC

## Dedicated Screwdrivers

		Machine Screw(2.6 - 8.0 mm)							Built-in brushless motor					
Model	Lever Start	DLV7120-SPC	DLV7130-SPC	DLV7140-SPC	-----	DLV7251-SPC	DLV7241-SPC	DLV7231-SPC	DLV30LL-SPC	DLV30SL-SPC	DLV30HL-SPC	DLV45LL-SPC	DLV45SL-SPC	DLV70LL-SPC
	Push to Start	DLV8120-SPC	DLV8130-SPC	DLV8140-SPC	DLV8150-SPC	DLV8251-SPC	DLV8241-SPC	DLV8231-SPC	DLV30LP-SPC	DLV30SP-SPC	DLV30HP-SPC	DLV45LP-SPC	DLV45SP-SPC	DLV70LP-SPC
Input Voltage		100/230 V AC, 50/60 Hz												
Torque Adjustment		Stepless												
Torque (Nm)		0.25 - 0.75	0.5 - 1.7	1.2 - 3.0	2.0 - 4.5	2.0 - 4.5	1.2 - 3.0	0.5 - 1.7	0.4 - 1.6/1.2 - 3.0			2.0 - 4.5		3.8 - 7.0
Free Speed (min <sup>-1</sup> )		1,000		700	450	700	1,200	2,000	650	1,200	2,000	650	1,200	650
Power Consumption (W)		35					45							
Screw Size (mm)	Machine Screw	2.6 - 3.0	2.6 - 4.0	3.5 - 5.0	4.5 - 6.0	4.5 - 6.0	3.5 - 5.0	2.6 - 4.0	2.6 - 5.0			4.5 - 6.0		5.0 - 8.0
	Tapping Screw	2.3 - 3.0	2.5 - 3.5	3.0 - 4.0	4.0 - 5.0	4.0 - 5.0	3.0 - 4.0	2.5 - 3.5	2.5 - 4.0			4.0 - 5.0		4.5 - 6.0
Bit Type (mm)														
Mass (g)		710(7100series)/670(8100series)			810		710(7200series)/670(8200series)		700			870 with pistol grip		
Cord Length (m)		3 (with connector)												
Bit Grounding		Equipped as standard												